



CANOPY & DUCT CLEANING SERVICES LTD.

REPORT

XXXXXXXXXXXXXXXXXXXX

2016

**AHU's 1 & 2 SUPPLY & RETURN
DUCTWORK SYSTEMS CLEANING**

Unit 3
Colberts Fort
Belgard Road
Tallaght
Dublin 4
01 4524762
info@airways.ie



43 An Duiche
Scalaheen
Tipperary Town
Co. Tipperary
087 6501513
john@airways.ie

Report on XXXXXXXXXXXXXXXX

AHU's 1&2 supply and return air systems cleaning

All Areas:

- AHU's 1&2 supply ductwork in the roof plantroom were soiled
- AHU's 1&2 supply ductwork from the AHU's to roof plantroom were lightly soiled
- AHU's 1&2 return ductwork in the roof plantroom were soiled
- AHU's 1&2 return ductwork from the AHU's to roof plantroom were soiled

Action Taken:

- Cleaned 65% of the supply ductwork that was accessible see drawing for sections not cleaned
- Cleaned all the return ductwork
- Photographs taken before and after cleaning

Result:

- All areas left clean and tidy
- All systems left operational

AHU 1 Return air leg 1C



AHU 1 Return air leg 1C2



Before cleaning

After cleaning

AHU 1 Return air leg 1C1



AHU 1 Return air leg 1C3




AHU 1 Return air leg 1C4



Before cleaning

After cleaning

AHU 1 Return air leg 1A



AHU 1 Return air leg 1A1



AHU 1 Return air leg 1A2



Before cleaning

After cleaning

AHU 1 Return air leg 1B




AHU 1 Return air leg 1A



Before cleaning

After cleaning

AHU 2 Return air leg 2B



AHU 2 Return air leg 2C




Before cleaning


After cleaning



AHU 2 Return air leg 2A





Before cleaning



After cleaning



AHU 2 Return air leg 1




Before cleaning

After cleaning




AHU 2 Return air leg 1A



Before cleaning

After cleaning



AHU 2 Return air leg 1B



Before cleaning

After cleaning

AHU 2 Return air leg 1C



Before cleaning

After cleaning

Certificate of Cleanliness

This certifies that an inspection and cleaning has been carried out at

XXXXXXXXXXXXXXXXXX

AHU's 1&2 supply & return systems cleaning
& the following actions have been undertaken to HVCA Guide to Good Practice
TR/19

- Cleaned 65% of the ductwork on the supply on AHU's 1&2
- Cleaned all the return ductwork on AHU's 1&2
- Left all areas as found

Note

Recommend cleaning return systems yearly and supply systems every two years

Date: July 2014

Technician: Brian Waddick

Review date: July 2015

Director: Damien Waddick



Airways Ltd.

Unit 3, Colberts Fort, Belgard Road, Tallaght, Dublin 24 : Phone: 01 4524762: 087 8771264



The HVAC Inspection, Maintenance
and Restoration Association